

Rehabilitation Checklist – Mount Hardy Project



Hole ID	Date Drilled	Drill hole Coordinates (GDA94 Lat\Long or GDA94 Zone # UTM)	Rehabilitation (✓ or date completed)									Post-closure Monitoring (2017)						Notes and Comments	
			Drill holes plugged/capped	Drill spoils buried/backfilled	Sample bags/core removed	Sumps backfilled	Topsoil/vegetation replaced	Drill pad ripped	Access track ripped	Rubbish removed	Is radiation within background levels?	Date of Monitoring	Is site nominated for ongoing monitoring?	Is the site revegetated?	Are there signs of erosion?	Are there weeds?	Is there subsidence?		Is radiation within background levels?
12MHRC 001	Nov 2012	761948mE 7552979mN	✓	✓	✓	NA	✓	✓		✓	NA	Oct 2017		In progress	NO	YES	NO	NA	Revegetation is occurring slowly due to lack of rain. Rubber bush present – see APPENDIX 4
12MHRC 002	Nov 2012	765050mE 7554048mN	✓	✓	✓	NA	✓	✓		✓	NA	Oct 2017	YES	In progress	NO	NO	NO	NA	EM#2 - Limited vegetation growth – will visit after wet season and consider reseeding.
12MHRC 003	Nov 2012	764151mE 7550401mN	✓	✓	✓	NA	✓	✓		✓	NA	Oct 2017		In progress	NO	NO	NO	NA	Revegetation is occurring slowly due to lack of rain
12MHRC 004	Nov 2012	764700mE 7550509mN	✓	✓	✓	NA	✓	✓		✓	NA	Oct 2017	YES	In progress	NO	NO	NO	NA	EM#5 – Rehabilitating well – also access track rehabilitating well.
12MHRC 005	Nov 2012	762048mE 7552851mN	✓	✓	✓	NA	✓	✓		✓	NA	Oct 2017		In progress	NO	YES	NO	NA	Revegetation is occurring slowly due to lack of rain. Rubber bush present – see APPENDIX 4

12MHRC 006	Nov 2012	765050mE 7550453mN	✓	✓	✓	NA	✓	✓		✓	NA	Oct 2017		In progress	NO	NO	NO	NA	EM#2 - Limited vegetation growth – will visit after wet season and consider reseedling.
12MHRC 007	Nov 2012	761939mE 7552981mN	✓	✓	✓	NA	✓	✓		✓	NA	Oct 2017		In progress	NO	YES	NO	NA	Revegetation is occurring slowly due to lack of rain. Rubber bush present – see APPENDIX 4
13MHDD H001	Mar 2013	766432mE 7552941mN	✓	✓	✓	✓	✓	✓		✓	NA	Oct 2017		In progress	NO	NO	NO	NA	Revegetation is occurring slowly due to lack of rain
13MHDD H002	Mar 2013	766405mE 7553004mN	✓	✓	✓	✓	✓	✓		✓	NA	Oct 2017		In progress	NO	NO	NO	NA	Revegetation is occurring slowly due to lack of rain
13MHDD H003	Mar 2013	766483mE 7552968mN	✓	✓	✓	✓	✓	✓		✓	NA	Oct 2017		In progress	NO	NO	NO	NA	Revegetation is occurring slowly due to lack of rain
13MHDD H004	Mar 2013	766536mE 7553017mN	✓	✓	✓	✓	✓	✓		✓	NA	Oct 2017		In progress	NO	NO	NO	NA	Revegetation is occurring slowly due to lack of rain
13MHDD H005	Mar 2013	760866mE 7554801mN	✓	✓	✓	✓	✓	✓		✓	NA	Oct 2017		In progress	NO	NO	NO	NA	Revegetation is occurring slowly due to lack of rain
13MHDD H006	Mar 2013	760866mE 7554801mN	✓	✓	✓	✓	✓	✓		✓	NA	Oct 2017		In progress	NO	NO	NO	NA	Revegetation is occurring slowly due to lack of rain
13MHDD H007	Mar 2013	760866mE 7554801mN	✓	✓	✓	✓	✓	✓		✓	NA	Oct 2017		In progress	NO	NO	NO	NA	Revegetation is occurring slowly due to lack of rain
13MHDD H008	Mar 2013	760886mE 7554706mN	✓	✓	✓	✓	✓	✓		✓	NA	Oct 2017	YES	In progress	NO	NO	NO	NA	Browns - Hillside site. Limited vegetation growth – will visit after wet season and consider reseedling
13MHDD H009	Mar 2013	760886mE 7554706mN	✓	✓	✓	✓	✓	✓		✓	NA	Oct 2017	YES	In progress	NO	NO	NO	NA	Browns - Hillside site. Limited vegetation growth – will visit after wet season and consider reseedling

13MHDD H010	Mar 2013	761943mE 7552979mN	✓	✓	✓	✓	✓	✓		✓	NA	Oct 2017		In progress	NO	YES	NO	NA	EM#1. 2017 resulted in disturbance of this site and as such revegetation process was disrupted. Rubber bush present – see APPENDIX 4
13MHDD H011	Mar 2013	761849mE 7553098mN	✓	✓	✓	✓	✓	✓		✓	NA	Oct 2017		In progress	NO	YES	NO	NA	Revegetation is occurring slowly due to lack of rain. Rubber bush present – see APPENDIX 4
13MHDD H012	Mar 2013	765050mE 7554050mN	✓	✓	✓	✓	✓	✓		✓	NA	Oct 2017		In progress	NO	NO	NO	NA	EM#2 - Limited vegetation growth – will visit after wet season and consider reseeded.
13MHDD H013	Mar 2013	764177mE 7551451mN	✓	✓	✓	✓	✓	✓		✓	NA	Oct 2017	YES	In progress	NO	NO	NO	NA	EM#4 – Rehabilitating well – also access track rehabilitating well.
13MHDD H014	Mar 2013	766238mE 7552929mN	✓	✓	✓	✓	✓	✓		✓	NA	Oct 2017		In progress	NO	NO	NO	NA	Revegetation is occurring slowly due to lack of rain
13MHDD H015	Mar 2013	760902mE 7554549mN	✓	✓	✓	✓	✓	✓		✓	NA	Oct 2017	YES	In progress	NO	NO	NO	NA	Browns IP Target. Original hole site rehabilitating well
17MHRC 016	Apr 2017	760900mE 7554510mN	✓	✓	✓	NA	✓	✓		✓	NA								
17MHRC 017	Apr 2017	760897mE 7554601mN	✓	✓	✓	NA	✓	✓		✓	NA								
17MHRC 018	Apr 2017	761008mE 7554510mN	✓	✓	✓	NA	✓	✓		✓	NA								
17MHRC 019	Apr 2017	760815mE 7554602mN	✓	✓	✓	NA	✓	✓		✓	NA								
17MHRC 020	Apr 2017	766180mE 7552906mN	✓	✓	✓	NA	✓	✓		✓	NA								
17MHRC 024	Apr 2017	764928mE 7554057mN	✓	✓	✓	NA	✓	✓		✓	NA								

17MHRC 026	June 2017	766364mE 7552942mN	✓	✓	✓	NA	✓	✓		✓	NA								
17MHRC 027	June 2017	766400mE 7552945mN	✓	✓	✓	NA	✓	✓		✓	NA								
17MHRC 028	June 2017	766185mE 7552860mN	✓	✓	✓	NA	✓	✓		✓	NA								
17MHRC DDH021	April/ May 2017	761924mE 7552975mN	✓	✓	✓	✓	✓	✓		✓	NA								
17MHRC DDH022	April/ May 2017	761753mE 7553150mN	✓	✓	✓	✓	✓	✓		✓	NA								
17MHRC DDH023	April/ June 2017	764936mE 7554051mN	✓	✓	✓	✓	✓	✓		✓	NA								
17MHRC DDH025	May 2017	761857mE 7553052mN	✓	✓	✓	✓	✓	✓		✓	NA								
17MHRC DDH029	June 2017	764930mE 7554056mN	✓	✓	✓	✓	✓	✓		✓	NA								