

Walabanba MMP Monitoring Site Photographs



MS1_17WBRC002_AFTER
REHAB 1



MS1_17WBRC002_AFTER REHAB 2



MS1_17WBRC002_BEFORE REHAB



MS1_17WBRC002_PLUGGED



MS2_17WBRC006_AFTER REHAB



MS2_17WBRC006_BEFORE REHAB



MS2_17WBRC006_PLUGGED



MS3_Track_17WBRC002_003



MS4_Track_17WBRC004



MS5_Track looking south_17WBRC006



MS5_Track looking north_17WBRC006



MS6_TRMCamp_1



MS6_TRMCamp_2



MS6_TRMCamp_3



MS6_TRMCamp_4