

Provide details (where applicable) of the rehabilitation activities that were conducted during the past 12 months and from previous reporting periods.

Drill Hole/Pad Rehabilitation Status												
Tenement	Drill Hole ID	Easting (GDA 94 Zone 53)	Northing (GDA 94 Zone 53)	MMP Reference	Date Drilled	Drilling Method*	Size of Drill Pad (m ²)	No. of sumps	Status†	Rehab Date	Planned Rehab Date	Comments
EL26848	17WBRC001	301300	7621351	Auth. 0924-01	Jul 17	RC	300		C	Oct 2017		
EL26848	17WBRC002	301705	7621804	Auth. 0924-01	Jul 17	RC	300		C	Oct 2017		
EL26848	17WBRC003	301621	7621602	Auth. 0924-01	Aug 17	RC	300		C	Oct 2017		
EL26848	17WBRC004	301850	7621354	Auth. 0924-01	Aug 17	RC	300		C	Oct 2017		
EL26848	17WBRC005	304093	7595854	Auth. 0924-01	Aug 17	RC	300		C	Oct 2017		
EL26848	17WBRC006	304599	7595401	Auth. 0924-01	Aug 17	RC	300		C	Oct 2017		

* AC = aircore/vacuum, RM = rotary mud, RC = reverse circulation, RAB = rotary air blast, D = diamond, P = percussion, V = vibracore or sonic, O = other.

† C = drillsite completely rehabilitated (hole collar removed plugged and backfilled, drill spoils buried and sample bags removed, sumps backfilled, drill pads re-contoured and ripped, photograph taken), N = no rehabilitation completed, PR = partial rehabilitation (specify remaining rehabilitation to be completed within the comments section).

