

Provide details (where applicable) of the rehabilitation activities that were conducted during the past 12 months and from previous reporting periods.

Drill Hole/Pad Rehabilitation Status												
Tenement	Drill Hole ID	Easting (GDA 94 Zone 53)	Northing (GDA 94 Zone 53)	MMP Reference	Date Drilled	Drilling Method*	Size of Drill Pad (m ²)	No. of sumps	Status†	Rehab Date	Planned Rehab Date	Comments
EL26848	17WBRC001	301300	7621351	Auth. 0924-01	Jul 17	RC	300		C	Oct 2017		
EL26848	17WBRC002	301705	7621804	Auth. 0924-01	Jul 17	RC	300		C	Oct 2017		
EL26848	17WBRC003	301621	7621602	Auth. 0924-01	Aug 17	RC	300		C	Oct 2017		
EL26848	17WBRC004	301850	7621354	Auth. 0924-01	Aug 17	RC	300		C	Oct 2017		
EL26848	17WBRC005	304093	7595854	Auth. 0924-01	Aug 17	RC	300		C	Oct 2017		
EL26848	17WBRC006	304599	7595401	Auth. 0924-01	Aug 17	RC	300		C	Oct 2017		

* AC = aircore/vacuum, RM = rotary mud, RC = reverse circulation, RAB = rotary air blast, D = diamond, P = percussion, V = vibracore or sonic, O = other.

† C = drillsite completely rehabilitated (hole collar removed plugged and backfilled, drill spoils buried and sample bags removed, sumps backfilled, drill pads re-contoured and ripped, photograph taken), N = no rehabilitation completed, PR = partial rehabilitation (specify remaining rehabilitation to be completed within the comments section).

Access Track/Drill Line Rehabilitation Status

Tenement	Track ID	Tracks/lines Created (km)	Rehab'd tracks/lines (km)	Status[†]	Rehab Date	Planned Rehab Date	Comments
EL26848		4.23		PR			Tracks are currently being inspected and monitored and will be remediated as necessary. They will be left to revegetate naturally.

[†] C = rehabilitation completed, N = no rehabilitation completed, PR = partial rehabilitation (specify remaining rehabilitation to be completed within the comments section).

Campsite Rehabilitation Status

Tenement	Camp Name	Date Est.	Easting (GDA 94 Zone 53)	Northing (GDA 94 Zone 53)	Camp Size (ha)	Status[†]	Waste Removed	Camp Rehab Date	Planned Rehab Date	Comments
EL26848	TRM	Jul 2017	310315mE	7601815mN	0.09	C	✓	Oct 2017		Campsites were adjacent to one another
EL26848	Drillers	Jul 2017	310315mE	7601815mN	0.09	C	✓	Oct 2017		Campsites were adjacent to one another

† C = rehabilitation completed, N = no rehabilitation completed, PR = partial rehabilitation (specify remaining rehabilitation to be completed within the comments section).